

A division of CMI Operations Pty Ltd ABN 87 088 279 270

Sydney 18-20 Railway Road Meadowbank NSW 2114 DBrisbane 485A Zillmere Road Zillmere QLD 4034 Postal Address: Locked Bag M3 Meadowbank NSW 2114 Postal Address: PO Box 642 Virginia QLD 4014 Telephone: (02) 9807 6155 Facsimile: (02) 9808 2033

□ Melbourne 3-5 Dissik Street Cheltenham VIC 3192 □ Rockhampton Shop3, 76 Hollingsworth St Telephone: (03) 9532 1233 Facsimile: (03) 9553 3502 North Rockhampton QLD 4701

Perth 36 Division Street Welshpool WA 6106 Telephone: (08) 9358 1788 Facsimile: (08) 9358 1733 Telephone: (07) 4921 0978 Facsimile: (07) 4921 0981

Telephone: (07) 3863 0749 Facsimile: (07) 3863 0795

Postal Address: PO Box 1124 North Rockhampton QLD 4701

For all account enquiries Phone (02) 8878 1320 Fax (02) 9808 4977

CMI ELECTRICAL INDUSTRY NOTICE 25th March 2022

Re: CMI / MINTO 300/425A Restrained Receptacles minor drawing documentation issues. Certification Nos: ANZEx 13.3002; IECEx TSA 13.0005X

CMI Electrical are notifying the industry that minor documentation issues have been identified with Certification Drawings for the above products.

This issue will require a supplementary certification to correct some information on the drawings for these products.

This will take place over the next month and revised drawings will be available on the CMI Electrical website when they are issued.

During this investigation, we had the products fully assessed by our certification body, TestSafe, and they have issued the following statement:

" I wish to confirm that we have reviewed the information provided, the relevant certification drawing and the associated manufacturing drawings related to the product covered by the above certificate.

The product was tested and passed all tests as required by IEC 60079-0 and IEC 60079-1. There is no safety issue identified with the product.

However, there are discrepancies on the certification drawing which will require a supplementary certificate to be issued to correct it."

Note:

We have become aware of unsolicited information circulating in the industry that these products have a major non-compliance.

This is un-true, refer to the above statement from TestSafe. This type of information can disrupt confidence in both products and manufacturers.

For additional information, refer to the CMI Electrical website: www.cmielectrical,com.au

CMI Electrical Pty Ltd

Michael Page Manager Mining and Operations



